



<u>Risk Assessment – Lasers</u>							
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Laser light	Eye damage		SWMS / Permit to work	Admin	2		PCBU. S.
			Tool box talk	Admin	2		S.
			Supervision of workers	Admin	2		PCBU. S.
			Training of workers	Admin	2		PCBU. S.
			Site induction	Admin	2		PCBU. S.
			Exclusion zones	ISE	3		PCBU. S. W.
			Signage	ISE	3		PCBU. S. W.
			Set laser above or below eye level	ISE	3		PCBU. S. W.
	Appropriate PPE – eye protection			PPE	1	ALARP	PCBU. S. W

ALARP = As low as Reasonably Practicable. You must monitor worker compliance with the SWMS.