

Risk Assessment – Work near areas with Radiation							
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Infectious disease	Death or health hazard	25E	SWMS / Permit to work	Admin	2	22	PCBU. S.
			Tool box talk	Admin	2		S.
			Supervision of workers	Admin	2		PCBU. S.
			Training of workers	Admin	2		PCBU. S.
			Site induction	Admin	2		PCBU. S.
			Exclusion zones	ISE	3		PCBU. S. W.
			Signage	ISE	3		PCBU. S. W.
			Consultation with medical & radiation professionals	Admin	2		PCBU. S.
			Decontamination of work area	ISE	3		PCBU. S.
		Appropriate PPE	PPE	1	ALARP	PCBU. S. W	

ALARP = As low as Reasonably Practicable. You must monitor worker compliance with the SWMS.