



<u>Risk Assessment – Silica Dust</u>							
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Dust	Health	16E	SWMS / Permit to work	Admin	2	14	PCBU. S.
			Tool box talk	Admin	2		S.
			Supervision of workers	Admin	2		PCBU. S.
			Training of workers	Admin	2		PCBU. S.
			Site induction	Admin	2		PCBU. S.
			Consider dust extraction	ISE	3		PCBU. S. W.
			Appropriate PPE Mask	PPE	1	ALARP	PCBU. S. W.
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Repetitive tasks	Serious bodily injury	20E	SWMS	Admin	2	17	PCBU. S.
			Tool box talk	Admin	2		PCBU. S. W.
			Supervision	Admin	2		PCBU. S.
			Risk assessment / SWMS	Admin	2		PCBU. S. W.
			Specific task training	Admin	2		PCBU. S. W.
			Breaks	Admin	2		PCBU. S. W.
			Rotate workers	ISE	3		PCBU. S. W.
			VOC for the task	Admin	2	PCBU. S.	
						ALARP	

ALARP = As low as Reasonably Practicable. You must monitor worker compliance with the SWMS.

A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Fit for work	Bodily injury, damage to property and other workers	12E	SWMS	Admin	2	8	PCBU. S.
			Tool box talk	Admin	2		PCBU. S. W.
			Supervision	Admin	2		PCBU. S.
			Assess suspect workers before work commences	Admin	2		PCBU. S. W.
						ALARP	
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Incorrect use of PPE	Personal injury	12E	SWMS	Admin	2	11	PCBU. S.
			Tool box talk	Admin	2		PCBU. S. W.
			Supervision	Admin	2		PCBU. S.
			Training in use of PPE	Admin	2		PCBU. S. W.
			Face fit test for RPE (asbestos & toxic dust)	ISE	3		PCBU. S.
						ALARP	
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Sharps & sharp objects	Cuts and punctures	12E	SWMS	Admin	2	9	PCBU. S.
			Tool box talk	Admin	2		PCBU. S. W.
			Supervision	Admin	2		PCBU. S.
			Risk assessment / SWMS	Admin	2		PCBU. S. W.
			Wear gloves when handling sharp objects	PPE	1		PCBU. S. W.
						ALARP	

ALARP = As low as Reasonably Practicable. You must monitor worker compliance with the SWMS.