



Risk Assessment – Asbestos in the workplace

A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Exposure to asbestos	Death	20E	Asbestos Register	Admin	2	17	PCBU. S.
			Tool box talk	Admin	2		S.
			Appointment of person to manage ACM	Admin	2		PCBU. S.
			Training of workers	Admin	2		PCBU. S.
			Site induction	Admin	2		PCBU. S.
			Exclusion zones	ISE	3		PCBU. S. W.
			Signage	ISE	3		PCBU. S. W.
			Appropriate PPE	PPE	1	ALARP	PCBU. S. W
A. Hazard	B. Potential Risk What Goes Wrong	C. Risk Score	D. Risk Controls	E. Control Type		F. Res Risk Score	G. Person Responsible
Disturbance of ACM	Death	20E	Asbestos Register	Admin	2	17	PCBU. S.
			Tool box talk	Admin	2		S.
			Licensed trades to disturb ACM	Admin	2		PCBU. S.
			Training of workers	Admin	2		PCBU. S.
			Site induction	Admin	2		PCBU. S.
			Exclusion zones	ISE	3		PCBU. S. W.
			Signage	ISE	3		PCBU. S. W.
			Appropriate PPE	PPE	1	ALARP	PCBU. S. W

ALARP = As low as Reasonably Practicable. You must monitor worker compliance with the SWMS.